How to solve FEM fail to do mileage reset


Do milegae reset , If it shows you SWFL_0000155E_018_120_010 in the pic ,means it

not support to do mileage reset .

How to solve it ?

We go to BMW F/G series program page ,Then choose advanced mode

Choose SWFL_0000155E_017_110_030 version ,then to program (make sure battery

voltage is enough)

Make sure SWFL_0000155E_017_110_030 version program succeed . Better back to

FEM/BDC key match   page to check the version again

Then you need to do reprocessing steps again .

Then the mileage reset can work